

10.2 Example Problem 2

A fired crude heater experienced a temperature excursion for a short duration. The refinery needs to know how much additional damage occurred to the tubes to understand how the excursion impacts the remaining tube life. This information will be used to help determine if the heater will need to be re-tubed at an upcoming scheduled turn-around, or if the tubes are likely to last for another run. Evaluate the tube remaining life (typical past history plus known temperature excursion) and determine if they are fit for service for another run.

Heater Tube Data

• Material	=	SA-335 Grade P22 Year 1998
• Typical Conditions (j=1)	=	210 psig @1115 °F
• Outside Diameter	=	8.625 in
• Fabricated Thickness	=	0.322 in
• Future Corrosion Allowance (FCA)	=	0.10 in
• Weld Joint Efficiency	=	1.0
• Unsupported Length	=	144 in
• Cylindrical Shell		
• Past Operating Time (j=1)	=	131400 hours
• Past Operating Time (j=2)	=	336 hours
• Future Expected Time (j=1)	=	43800 hours

Temperature Excursion Data

• Excursion Pressure:	=	210 psig
• Excursion Temperature:	=	1220 °F
• Excursion Duration:	=	336 hours

Inspection Data

There are no visual signs of damage to the tube, no bulging, metal loss, or excessive scale was noted. UT thickness readings indicated light general metal loss within the original corrosion allowance. Looking through the inspection records, this is the first operational excursion into the creep range for this component. There are no weld seems in the fire box.

Perform a multiple condition Level 1 Assessment for the component in creep service per paragraph 10.4.2.2 Each component of the vessel must be analyzed separately. In this example, the tube bends are located outside the firebox, so only the cylindrical portion of the tubes will be analyzed. For the purposes of this example, assume the tubes are adequately supported and that circumferential pressure stress is the limiting design condition.




Fig. 9. The tensile hysteresis energy versus number of cycles to failure

CONCLUSION

In this study, with specimens extracted from aged boiler header in a power plant, the isothermal low cycle creep-fatigue tests are performed. The results are as follows.

1. At a given strain range, the fatigue life decreases with increasing hold time. There seems to be a saturation effect, no further reduction of the fatigue life above 600 s hold time is apparent by the long creep effects.

2. The tensile hysteresis energy approach for in-serviced material tests is introduced. This correlated to the number of cycles to failure by the relationship, $\sigma_f \Delta \varepsilon_p N_f^B = C$. Comparison of calculated values with experimental results shows good agreement.




Fig. 10. Measured life versus predicted life

CREEP-FATIGUE LIFE PREDICTION OF AGED 13CrMo44 STEEL USING THE TENSILE PLASTIC STRAIN ENERGY

GEEWOOK, SONG, JUNGSEOB, HYUN, JEONGSOO, HA

Korea Electric Power Research Institute (KEPRI),

103-16, Daejeon, Korea

ABSTRACT

Low cycle creep-fatigue tests of 13CrMo44 steel used for boiler header of fossil power plant for 185,000 hr are conducted at 515°C with triangular and trapezoidal strains wave. Trapezoidal wave is considered about hold time for creep effects. The relationship between the tensile hysteresis energy and number of cycles to failure is examined to predict the low cycle creep-fatigue life of 13CrMo44 steel. The life, predicted by the tensile hysteresis energy method, is found to coincide with experimental results and analytical results obtained from models such as Coffin-Manson method.

KEYWORDS

13CrMo44 steel, plastic strain energy, creep-fatigue interaction, tensile hysteresis energy, boiler header, life prediction.

INTRODUCTION

The power plants use high temperature and high pressure for good thermal efficiency and these components of a power plant such as boiler header, steam pipe, turbine rotor and casing, etc. may undergo low cycle fatigue at high temperature. These critical components are subjected to transient loadings resulting from the large number of start-up and loading changes induced by the daily and seasonal variations in the electricity demand. Thus, most materials of components used in conditions of high temperature and high pressure suffer from thermal stresses as well as mechanical stresses. Although actual low cycle fatigue fracture is caused by thermal stresses due to the temperature changing, the behavior of materials is customarily investigated at constant temperature under mechanical loading.

Previously, most of the evaluation of low cycle fatigue life of materials has been done at uninterrupted (triangular) cycling. Correlation with actual service experience using this data is not encouraging. Therefore, introducing hold times makes a simulation closer to the actual service conditions. Since the fatigue damage is generally caused by the cyclic plastic strain, the plastic strain energy plays an important role in the damage process. Therefore, the idea of relating fatigue life to the plastic work during a load cycle has been proposed [1-5]. In this approach, plastic strain energy was proposed by Morrow. Ellyin proposed a fatigue failure criterion based on the strain energy density damage law. Ostergren proposed the net tensile hysteresis energy that can be used as the damage function. The objective of this paper is the investigation of the effect of hold time in the creep-fatigue tests and evaluate remaining life of the 185,000 hr, 439 start-up, aged 13CrMo44 steel by using the tensile hysteresis energy as the measure of creep-fatigue damage per cycle.

Inter Connecting Chamber

4

Insulating Layer
Plicast LWI 22 R/G

15CuNiMoNb5

13CrMo44 (T12)
Rect Pitch : 52 vert x 88 horiz (mm)

Outlet Tube sheet
13CrMo44 (T12) n thick

Hot Face Layer
Plicast D40K


Inlet Tube sheet &
13CrMo44 (F12) with
Stiffener assembly


Recessed Face groove weld
joint

TTS Joint

EXPANSIONS
LENGTH

200 mm Expansion
with strength weld





Waste Heat Boiler Related Literature References

Sr No.	Relevant or Not Relevant	Year	Title	Description	Brief Summary	Construction details etc.	Installed Location and Designer
1	Not relevant. Vertical.	1960	Failure of a Primary Waste Heat Boiler	Failure of pressure shell due to refractory. Indications are that silica-based castable refractories lose insulating properties when used in reducing atmospheres, and under the temperature pressure conditions in the steam-methane section of an ammonia plant.	Failure of pressure shell due to refractory. Indications are that silica-based castable refractories lose insulating properties when used in reducing atmospheres, and under the temperature pressure conditions in the steam-methane section of an ammonia plant. Refractory type and size to be substituted.	Vertical	Terra Chemicals International/Israel.
2	Partially relevant w.r.t. BFW quality and gas inlet/out etc.	1976	Waste Boilers: Problems & Solutions	Discussion on different failures and possible remedial actions. A single failure of one of these units can easily result in a profit loss equal to the total cost of the boiler.	One could have different failures and possible remedial actions. A single failure of one of these units can easily result in a profit loss equal to the BSE cost of the boiler.		
3	Partially relevant	1979	Waste Heat Boiler Failure and Modifications	Failures and subsequent repairs eventually resulted in the decision to replace these boilers with a new double compartment design.	Two waste heat boilers. Thick tubeshheet 50 mm replaced with 20 mm thin tubeshheet in modified design. Cooling tubes of tubes with less flexibility in thick tubeshheets. Stress concentration at weld root due to gap between tube and tubeshheet at rolled portion increases in thick tubeshheet design. Single compartment replaced with double compartment design. By reducing the tubes length the differential expansion is reduced to approximately half of its value with gradient reduction in the tube sheet deflection. Tubes material was changed to 3.34 ksi in modified design. The use of tube and sheet material of 6.0 kSis is intended to minimize welding stresses and improve the reparability and also permitted the use of full penetration weld without the need to stress relieving. The full penetration weld eliminated the stress for stress concentration as in rolled and face welded type.	Horizontal single Compartment, Tube sheet material 13 Cr. Mo 44 (11/4 Cr. 1/2 Mo) Tubes material 13 Cr. Mo 44 Ferritic alloy 800 1/2 230 mm, long. 1.8 metre dia and 12.5 metre long. Designed according to DIN standards	Petrochemical Industries Kuwait
4	Not relevant. Vertical.	1985	Failure and Repair of the Shell of a Primary Waste Heat Boiler in a 1,500 ton/d Ammonia Plant	A primary waste heat boiler shell cracked at a 1,500 ton/d Kellogg ammonia plant failed to operate. Inspection and repair procedures, results of failure analysis, and methods for avoiding future failures are outlined.	Analysis of the failure revealed an extensive surface cracking pattern on the OD surface of the waste heat boiler shell extending downward to the center-line of the process gas outlet nozzle. The mechanism clearly involves localized corrosion, aggravated by periodic mechanical stress. The cracking involves a slow, step-like progression, and is not restricted to the water jacket portion of the shell. Thermally induced surface stresses due to liquid metal fluctuations, local boiling, or splashing with the water jacket was initially accepted as the failure mechanism. However, such conditions of corrosion and surface stress were not obvious at the flange weld above the water jacket. To alleviate the corrosion problem, the FERRINIS is considering if coating the upper exposed area of the shell of the boilers during the next turnaround, and (2) the use of oxygen scavenger to reduce the corrosivity of the cooling water. In addition, the water jacket will be raised such that the water will cover the shell up to, and including, the flange weld.	Vertical Bayonet Type. A 1516 70 shell	Fertilizers of Trinidad & Tobago Ltd., Point Lisas, Trinidad
5	Vertical. General discussion on TTS joint cracking.	1986	Improving Reliability of Waste Heat Recovery Units in Ammonia Syn Loops	Incidents of leaks experienced during operation of boiler feed water heaters/boilers in syn loops led to good repair procedures and current design concepts.	It is evident that there is not one single mechanism causing failure of tube-to-tubeshheet joints in WHRUs/1. Periodic cracks may induce stresses in the tube-to-tubeshheet joints which can cause eventual fatigue of the joints. Hydrogen attack may be enhanced by metallurgical problems resulting from poor fabrication techniques and periodic temperature excursions. Its design is absolutely foolproof. However, the present design and choice of metallurgy are considered adequate for these service conditions. The current metallurgy should offer satisfactory reparability in the event tube-to-tubeshheet joints do crack. In addition, Kellogg is continuing to develop new designs which will eliminate more of these undesired problems.	Literature study	Fertilizers of Trinidad & Tobago Ltd., Point Lisas, Trinidad
6	Not relevant	1987	Failure and Repair of a Primary Waste Heat Boiler	Rupture occurred in the bottom dished head of the primary waste heat boiler in a 1500 T/d ammonia plant after two-year operation. Extensive in situ metallography, mechanical testing, and nondestructive examinations were performed to determine the integrity of the bottom shell course and inlet nozzle.	Metallography and mechanical testing established that there was no deterioration in the property of the bottom head material even close to the failure. Decarburization was confined to the surface and the fine grain structure of the metal indicated there was no prolonged exposure to high temperatures. The absence of voids or fissures in the decarburized layer and good ultrasonic sound transmission discouraged hydrogen attack. The rupture of the bottom head was concluded to be as a result of localized refractory damage and short term high temperature stress rupture. The reason for refractory failure could not be determined as all evidence was destroyed in the rupture. The first shell course, gas inlet nozzle and bottom dished nozzle were in good physical, metallurgical and weldable condition and could be reused.	Vertical. Irrelevant failure. The shell is made of ASTM A 516 Gr. 70 carbon steel internally lined with 97% bivalent alumina castable. The refractory is protected from erosion and collapse by lower thick stainless steel shroud sections that fit together with expansion joints.	Kellogg ammonia plant of P.T. Pupuk Kalimantan Timur located at Bontang, East Kalimantan, Indonesia
7	BFW quality is very important in operation of WHB	1988	Problems with a Process Gas Cooler	Poor boiler feed water quickly corrodes tubing in the tube boiler with a high heat flux at the gas inlet, as evidenced in Duchsala's process gas cooler.	Higher contents of iron and copper and low pH-values lead to severe corrosion. Due to poor raw water quality and a failure in the water treatment plant the iron content of the boiler feed water rose up to a level more than 30 times higher as specified. In addition the pH-value dropped down from 9 to below 5 for some hours. These incidents occurred twice.	Horizontal, dual compartment, corrosion of tubes, 1973 16 tubes repaired, 1978 totally retubed, 1986, first compartment repaired. Gas side shells, tube sheets and tubes are fabricated from C-27 Mo-steel.	Ammonia plant of Duchsala in Czechoslovakia, which has a capacity of 1000 TPD, was commissioned in 1973
8	General discussion on tube-to-tubeshheet joints improvement and utilization of thin tubeshheets.	1988	Experience with a New Design of Reformer Waste Heat Boiler: Synthesis Steam Generator, and Steam Superheater	A new design of thin tubeshheet straight tube reformer waste heat boiler, synloop steam generator, and steam superheater are discussed. Improvements in design increase the reliability of boilers.	The new Balcis Durr design concept for the reformer waste heat boiler is unique and offers many advantages over other designs. A thin tubeshheet can now be utilized without complex offsetting members. The hydraulic expansion process provides precise fire tube supports and adds operating integrity to the tubsheet weld. In the event that a repair is necessary, the removal and replacement of a tube is a fairly simple postweld heat treatment is not required. The first of these units has operated successfully in NDM's new plant for about one year.		
9	Vertical. Guidelines on protecting magnetite layer.	1989	Problems with the Magnetite Layer in Primary Waste Heat Boilers and Auxiliary Boilers	After 18 years of operation, the auxiliary and the first waste heat boiler downstream of the secondary reformer leaked due to corrosion. Some heat repairs of October 1988, on signs of tube failure, were detected.	Steps taken to protect magnetite layer are discussed.		BASt, Germany
10	Not relevant	1990	Post-Weld Heat Treatment of a Repaired Synloop Waste Heat Boiler	Repair of leaking tube-to-tubeshheet connections after repairs post-weld heat treatment. This can create a problem, since the tubeshheet is hardened in expansion by the exchanger head and shell. A local conductive heat treatment procedure can overcome this problem.	Experience of local heat treatment of TTS joints is discussed as PWHT of complete tubeshheet can cause cracks in TTS joints.		DSM Fertilizers Netherlands, Kellogg Ammonia technology plant
11	Not relevant. Water tube vertical boiler	1990	Use of Corrosive Thermal Barrier Coating in a Waste Heat Boiler	Use of Corrosive Thermal Barrier Coating in a Waste Heat Boiler	To avoid metal dusting on outside surface of tubes, plasma sprayed ceramic coating was applied.		Arasdan Memphis ammonia plant, Foster Wheeler design
12	Not relevant. Vertical.	1991	Failure of Waste Heat Boiler Downstream of Secondary Refiner	Failure of Waste Heat Boiler Downstream of Secondary Refiner	Discussion on improvement of design features.		Krishna Bharati India. Ammonia plants designed by Kellogg USA
13	Not relevant	1992	Tensile Ductility of Damaged Gas Distributor Avoided Failure of Unit	Tensile Ductility of Damaged Gas Distributor Avoided Failure of Unit			Krishna Bharati India. Ammonia plants designed by Kellogg USA
14	Not relevant. Synthesis Section WHB.	1993	Failure of Synthesis Waste Heat Boiler by Rotating Ferrules	Failure of Synthesis Waste Heat Boiler by Rotating Ferrules			
15	Not relevant. Synthesis Section WHB.	1993	Repair of Waste Heat Boiler in Synloop of NDS-Plant	Repair of Waste Heat Boiler in Synloop of NDS-Plant			
16	Not relevant. Synthesis Section WHB.	1994	Tube Failure in a Waste Heat Boiler Ammonia Synthesis Section	Tube Failure in a Waste Heat Boiler Ammonia Synthesis Section			
17	Not relevant. Case Studies 1 Methanol plant, 2 tube bundle, 1 Fertilizer & Refinery Vertical exchanger	1994	Failures in Waste Heat Boilers	Failures in Waste Heat Boilers			
18	Not relevant. Vertical.	1994	Ammonia Plant Waste Heat Replacement	Ammonia Plant Waste Heat Replacement			Sherritt Canada. Designed by Kellogg.
19	Not relevant.	1995	Experience with Metal Dusting in Waste Heat Boilers	Experience with Metal Dusting in Waste Heat Boilers			DSM Fertilizers Netherlands, Kellogg ammonia plant.
20	Partially relevant	1996	Catastrophic Failure of Tubeshheet in Fire Tube Reforming Gas Waste Heat Boiler	Catastrophic Failure of Tubeshheet in Fire Tube Reforming Gas Waste Heat Boiler			Tata (Covint) Canada. Equipment designed by Balmifield.
21	Not relevant. Water tube boilers. Vertical.	1996	Remedial Actions to Reformer Waste Heat Boilers	Remedial Actions to Reformer Waste Heat Boilers			Amiral Algeria. Kellogg designed plants.
22	Not relevant.	1996	Failure, Repair and Replacement of Waste Heat Boiler	Failure, Repair and Replacement of Waste Heat Boiler			
23	Not relevant. Shell Failures	1998	Ammonia Process Primary Waste Heat Boiler Shell Failure Experiences	Ammonia Process Primary Waste Heat Boiler Shell Failure Experiences			Canadian Fertilizers Canada. Kellogg designed plants.
24	Not relevant. Synthesis Section WHB. Vertical.	1999	Two Case Studies: New Concept WHB and Repair of BFW Reformer	Two Case Studies: New Concept WHB and Repair of BFW Reformer			
25	Not relevant. Failure of line connecting secondary reformer and WHB.	2001	Fire in Secondary Reformer Outflow Line to Waste Heat Boiler	Fire in Secondary Reformer Outflow Line to Waste Heat Boiler			
26	Not relevant.	2002	Selection of Nickel Base Alloys for Metal Dusting Resistance	Selection of Nickel Base Alloys for Metal Dusting Resistance			
27	Not relevant. Shell Failure	2003	Burst Before Leak Failure of a H ₂ S Effluent Waste Heat Boiler	Burst Before Leak Failure of a H ₂ S Effluent Waste Heat Boiler			DSM Agro. Kellogg designed ammonia plant
28	Not relevant. Synloop WHB outlet line. Vertical.	2003	Syn Loop Waste Heat Boiler Exit Line Failure	Syn Loop Waste Heat Boiler Exit Line Failure			
29	Vertical. Shells inserted to avoid leak shearing near bottom tubeshheet.	2003	Failures of Secondary Waste Heat Boilers	Failures of Secondary Waste Heat Boilers			Krishna Bharati India. Ammonia plants designed by Kellogg USA

31	Theoretical discussion on dynamic behaviour of WHBs	2004	Dynamic Behavior of the Waste Heat Boiler for Ammonia Plant	Non-stationary operating cases like start-up, shut-down or quick trip conditions which can be caused for example due to the loss of the boiler feed water lead to the additional stresses in the pressurized parts of the waste heat boiler. The paper describes the calculation of the pressure and temperature changes on the water side of the waste heat boiler for some transient operating cases. The temperature changes on the water and gas side determine the temperature distribution as well as the time dependent stress distribution in the pressurized parts of the waste heat boiler. The lifetime of the waste heat boiler can be affected.		
32	Not relevant. Water tube boiler.	2005	Waste Heat Boiler (102-C) Leakages & Possible Causes	Waste Heat Boiler 102-C is an essential part of Ammonia Plant in Kellogg design. Almost every plant is facing the problems of no flow, reverse flow and tube leakage. These problems are more significant on the plants where production capacity has been increased. In this article flow in the risers is considered. How flow is checked and a method is proposed to establish and maintain equal flow in both the risers.	DH	Dawood Hercules Lahore, Plant designed by Kellogg
33	Related to BFW quality issues	2005	Corrosion damage in Waste Heat Boilers; Major root causes and remediation	The crucial factor determining damages of high-pressure waste heat boilers in ammonia plants are fouling of the boiler tube surface with magnetite (Fe3O4) in combination with exceptionally high local heat fluxes. The main reasons for the magnetite fouling are: (I) Flow Accelerated Corrosion (FAC) in the preboiler / feed water system (II) First Condensate Corrosion (FCC) in steam and condensate equipment (III) Ineffective chemical cleaning and conditioning programs for the boilers The main goal of boiler water treatment programs should be to keep the boiler heat transfer surface free from deposits. Conventional chemical treatment programs are not always successful. Polyamine treatment can offer an alternative approach.		Plant 1 (AFA-2) in 1971, plant 2 (AFA-3) in 1984, Betschell and Kellogg technology. AFA-2 WHB dual compartment, AFA-3 WHB Single compartment
34	Relevant	2005	SECOND FAILURE OF REFORMED GAS WASTE HEAT BOILER	On 21st August 2004, the Ammonia plant had to be emergency shut down due to instrument air failure, after the feed gas and process steam was stopped to Primary Reformer and also process air stopped to Secondary Reformer. The acid header vent was still venting a lot of saturated steam from the gas stream side. Therefore, it might be concluded that the Reformed Gas Waste Heat Boiler 1-4-108 failed. This was the second failure after three years; previously, on 09 May 2002 tubing was found at circumferential weld line of the inlet channel failed of waste heat boiler about 250 mm from the inlet of tube sheet. This paper reports the experience of repairing the second failure of this particular waste heat boiler.		Design Borrig, Manufacture Kawasaki, second failure after three years. Tube repaired in october 2002 leaked in august 2004. Tubes failed due to inadequate PWT in first repair.
35	Not relevant. Refinery.	2005	Failure of 110 bar WHB's due to poor quality boiler feed water	Petrofin, formerly known as Mossgas is a 36000 bpd Gas to Liquid (GTL) plant situated at Mossel Bay in South Africa. This plant has been in operation since 1992 and the plant produces synthetic fuels from syngas gas. The synthesis gas is produced by reforming natural gas in a three-train combined reforming plant utilizing both primary tubular steam reforming and oxygen-blown auto thermal reforming. The front end of the plant layout incorporates a gas reforming unit, which was designed on the principle of the Lurgi Combined Reforming process. The facility was shutdown in May 2003 for its 10 yearly T&M. After commissioning of the three Reformer trains at its Waste Heat boilers developed boiler feed water leaks in excess of 60 tons per hour BFW of poor quality caused the failure of the WHB's tubes that resulted in a complete factory shutdown. This incident resulted in a comprehensive failure analysis. Several system improvements were considered and the modifications were implemented prior to the restart of the plant reformer trains.		Six WHBs developed boiler feed water leaks due to poor water quality management within 10 days of startup after TA. All six WHBs had to be replaced. By the end of next month who 4 ordered an replacer in next six months. Insulating magnetite layer resulted in overhauling of tubes. The waste heat boiler is a special shell and tube exchanger.
36	Partially relevant.	2005	Failure of REFORMED Gas Boiler Tubes: A Learning in Harder Way	Tube failure in any boiler is a common phenomenon, the analysis of data and conclusions derived, sometimes may be so misleading, it prevents laying hands on simple mistakes or defects. A similar kind of situation was encountered by KPIFL. From this experience it is learned, that however big a problem is, one should start from very basic fundamentals, rather than straightaway thinking in a complicated way.		Tube failure incidents. BFW quality issues and malfunctioning of valves etc. are discussed.
37	Not relevant. Synthesis loop WHB. Vertical	2006	Life Extension of Waste Heat Boilers in Ammonia Plants	Life extension measures can significantly increase the total lifetime of equipment. If they are done correctly and in time, they "buy time" until replacement equipment is available and reduce the risk of unplanned outages. The described solutions are not only limited to case of failures, gas flow reversal or modification to hot/cold alternating tubes can be applied to prolong the total lifetime of the equipment.		
38	Not relevant. Refractory issues are discussed	2006	Waste Heat Boiler (101C) Refractory Management	This paper shows the problems that Petrobrasil/Fallen-SF faced with two waste heat boilers in relation to the lining design and refractory losses. The lining was found almost completely destroyed at the first start-up of the plant. It shows how plant personnel managed to run the plant in spite of the lack of refractory that caused the water jacket to boil and the procedures that were adopted in order to keep the plant in operation until the turnaround. It also shows the details (region, extension, etc.) of the damage of the refractory and lining, the modification performed in the equipment and the way we now monitor the refractory integrity.		
39	Not relevant. HTS catalyst recovery incidents discussed.	2007	Successful Recovery from Major WHB Failures Experience	An all too common experience in the ammonia industry is the leaking of the waste heat boiler (WHB) located downstream of the acetaldehyde reformer. A significant tube leak of the WHB usually results in a subsequent flow of boiler water into the high Temperature (200 °C) WHB reactor, causing thermal shock to the catalyst bed, flooding the reactor, and preventing continued operation of the plant. In addition to the required WHB repairs, the change-out of the HTS catalyst tubes sometimes required. Terra Industries has experienced two recent significant WHB failures at different manufacturing sites.		
40	Relevant	2007	Failure of Damaged Tubes of the Reformed Gas Waste Heat Boiler at Proferit	Proferit commissioned their 200 MTPO Ammonia plant in January 2001. Since then the Reformed Gas Waste Heat Boiler has had repeated failures for various reasons. Tube plugging or partial tube replacement can be performed for replacement in case of new failure but with low reliability owing to the structural state of remaining tubes and high load limitations. No additional information is available to predict future failure at the equipment, yet there is a high probability of failure repetition. As a final result, it is essential to stress the need for highly safe and reliable safety facilities because their impact on plant operations is huge and to ensure, at all times of plant life, a proper treatment of the alterations.		
41	Not relevant. Watertube boilers discussed. Vertical WHB tube failures discussed.	2008	A Waste Heat Boiler Replacement – From Baymont to First-Tube	The baymont WHB 101-C after the secondary reformer that operated smoothly for 20 years faced frequent failures after the plant revamp. Chemical cleaning of the old BFW/Oxygen system performed during the revamp was a disaster. The water chemistry control was improved to avoid corrosion. However, major cause of the failure was oxygen/water circulation in one of the risers. A signal baffle was installed but, for a future plant revamp, the 101-C was replaced with a new fire-tube exchanger. The paper presents operational experience of waste heat boiler, tube failure analysis, its rectification and details of exchanger's installation in a follow designed ammonia plant, where space availability was a major constraint.		
42	Partially Relevant	2008	Replacement of Reformed Gas Waste Heat Boiler at Terra Courtright Ammonia Plant	The Reformed Gas Waste Heat Boiler (C108, at Terra Courtright facility, a Stearns-miller designed equipment, was in service since 1985. During the 22 years, it had experienced one catastrophic failure, in 1995 after 5 years of service, which required replacement of the first section of the boiler. In the early years, several metal dusting related problems on non-pressure components were reported as well, mostly in the second section of the boiler, which were eventually solved by adopting different metallurgy. Subsequent to first compartment replacement in 1995, the boiler was in operation for the next 8 years without any signs of known failure. In 2003 and 2005, during the routine inspection of the boiler in turnarounds, it was observed that the outlet tube sheet of the first compartment developed numerous cracks in the ligament sections. This paper describes the type of failure observed on the tube sheet and the reasoning that went into the decision to replace the equipment in the year 2007. This paper also highlights the activities that were involved in the design, procurement, onsite assembly & disassembly and installation of the waste heat boiler.		During the 1995 replacement job the first section was re-designed by Stearnsmiller to reflect the 115% operating rate of the plant. The revised design of the first compartment had two different tube sizes. Complete replacement with single compartment design in 2007
43	Not Relevant. Synthesis WHB.	2011	Ammonia Synthesis Loop Waste Heat Boiler Failure at GINFC	GINFC Ltd, Bharuch, India experienced two similar failures in the synthesis loop WHB. The failures occurred on two boilers of the same design but manufactured by different fabricators. This paper presents the details of the failure of the waste plant, the inspection, and the repair procedure adopted. The failure analysis was carried out at different levels to reach to the root cause of the problem and also to address all the possible causes. Recommendations of Halder Topsoe and metallurgical failure action plan to avert such failures are also described.		The failures occurred on two boilers of the same design but manufactured by different fabricators. The failures were at the same weld locations both happened within the first two failure years of operation. The first failure was confirmed to be a PWT problem. The in situ repair of the Borrig WHB worked well for more than 20 years and each inspection found no issues. They even passed the hydrotest of shell and tube side successfully. All above activities were performed in our presence but we were not witness to the most important aspects such as the removal of water from inside the tubes after hydrotest, subsequent drying of tubes by air and filling of nitrogen before dispatch. It seems that the above factors e. lack of care and attention to water removal, drying and nitrogen blanketing resulted in the formation of corrosion or rust deposits on the surface of tubes. These deposits got dislodged during service and hit at the bottom of outer tubes thereby blocking or reducing the specified gas flow between the bottom face of inner tubes and the bottom of outer tubes. The flow path was blocked leading to over-heating of tubes and ultimate rupture. Another factor, which is worth mentioning is the exact location of the tubes of the boilers, which failed repeatedly, in order to be more specific, if we see the location of ruptured tube as shown in Figure 3 and 2, we find that only peripheral tubes have ruptured subsequently damaging the nearby tubes. This indicates that there might have been some problem while inserting the tube bundle into the shell. There is a possibility of peripheral tubes being rubbed with the shell and consequently being damaged. During insertion of tube bundle into the shell, the bundle gets stuck-up in between & had to be pushed in forcibly as withdrawal at that stage would have distorted the shellcut.
44	Partially Relevant	2012	Successful Management of a 102C Waste Heat Boiler Leak by close and effective collaboration between Operator and Water Treatment Supplier	This paper captures the growing importance of the need for plant operators to engage Water Treatment Providers that understand all of the Operator's critical processes. Further, Water Treatment Providers should provide a range of supportive services that meet the original service mandate while continuing to add value during non-routine operation.		To ensure protection of the internal 1500 pipe (106.5 kg/cm2) boiler (steam generation surfaces from caustic pitting or acidic attack at this particular Operator site, a "coordinated phosphat" program, also referred to as a "coordinated phosphat" program (see Figure 2) was recommended. In summary, boiler leaks can be successfully managed while maintaining safe operational and production goals, through careful monitoring and maintenance of water chemistry. In this example, clear communication and planning led to orderly management and measurement of the parameters that affected plant operation and water treatment control, resulting in extended operation and realization of the Operator's production business plan.
45	Not relevant. Vertical	2012	Failure of Waste Heat Boiler in a Kellogg Designed Ammonia Plant	This failure pertains to a Kellogg designed Ammonia Plant of Indian Farmers Fertiliser Cooperative Ltd. (IFFCO) located at Phulpur, Allahabad, India. The twin Waste Heat Boilers (101-C&102) happened to be the most critical equipment of a Kellogg designed Ammonia Plant. These directly operated, baysonet type exchangers having inner and outer tubes with water cooled pressure shell have been the subject of great anxiety in recent past due to problems associated with the rupturing of their tubes, no flow of water or reverse flow through risers etc. The repeated failure of these exchangers caused due to rupturing of tubes twice in 3 months (May – August 2012) had cast a shadow on the energy, productivity and performance of the otherwise excellently performing 30 yr old plant. This article sheds light on the probable causes of failure, root cause analysis and more importantly, the threefold analysis of the methodology adopted for rectification so that plant can be returned back on stream in the shortest possible span of time and recurrence can be avoided.		Vertical boilers.
46	Not relevant. Watertube vertical.	2014	Lessons Learned From High Pressure Process Boiler Failure	After 15 months of service, a new 1500 pipe (103 barg) secondary reformer effluent process boiler developed a severe leak. After stabilizing the plant, operators identified the nature of the leak. Precautions were taken during the shutdown that were successful in preventing catalyst damage in the secondary reformer and AMF converter due to the leak of BFW into the process gas. The tube bundle was removed and replaced with a spare. The immediate cause of the failure was identified and a metallurgical analysis was performed on the failed and adjoining tubes. Possible contributing factors were considered. Metallurgical analysis results are consistent with the cause identified. Recommendations are shared on possibly recognizing this type of failure, shut down precautions, and prevention.		Period Circulation (not natural), Vertical, U tube. Tube Material incorrect G25
47	Not relevant. Synthesis loop. Vertical.	2015	Retaining experience of synthesis loop WHB No 1 and Failure of recycle WHB No 2	Synthesis loop waste heat boiler no 1: This boiler was replaced in year 2009 after being in operation for 12 years. In 2005, modifications were made to the external to reverse the flow which prolonged the life of the boiler. In 2002, a quality of boiler feed water (BFW) in steam boiler is reported in case of failure. Unexpected problems were found during tube which necessitated replacement of tube-sheet increasing project cost and schedule. This paper describes the re-tubing experience and the improvements done during re-tubing. Synthesis waste heat boiler no 2: The new boiler installed in year 2009 had 1000 tubes. Chloride analyses were done in the process to prevent stress corrosion cracking. Despite control mechanisms being in place, the boiler failed within 5 years. This paper describes the construction features of the boiler and the causes that contributed to the failure.		Vertical. Good feed.
48	Not relevant. Watertube boiler.	2015	Water-tube boiler	WHB 1 : Tubes inspected at random using RMS (Internal rotary inspection system) technique. Severe thinning of the tubes just after the flange on steam side was the reason for the above leak. The probable reasons for the failure attributed to corrosion under scale layers build up which were partly formed during PWT (heat wash treatment), but mainly deposited during operation by deposition of iron oxides from the water phase. Another contributing factor is low circulation rate on water side. (A similar phenomenon was noted also in the GINFC-4 plant in 2007. After re-tubing of steam condensate and optimisation of water treatment these deposits were found completely removed in 2008 and 20 22 inspections. WHB 2 : Based on above experience, it is essential to carry out internal bore washing to eliminate oxides in the tubes sheet to restrict chloride build-up. This is the only option if same materials are used for tube sheet and tube ends to the carryover internal bore washes. 2 U&G U 10 Mo material (T22 / P22) is the preferred if same material with density on the tube sheet.		

Nitrogen plus Syngas Magazine

Sr. No.	Year	Reference	Description
1	2000	0902 Page 33-35	20 incidents of failures, discussed shortly. (8 out of 20 incidents AIChE paper references available)
2	2000	0904 Page 33	One incident of failure due to scale build-up. Details not found yet.
3	2000	1112 Page 23	Failure of WHB due to change in water treatment programme. Details not available yet.
4	2001	0902 Page 7	Notes - 3 times plant shutdown in a year due to WHB leaks. Details not found yet.
5	2001	1112 Page 15	Conference Review - informed about failure of two WHB due to welding issues. AIChE paper reference available.
6	2002	0904 Page 15	Conference Review - KBR design WHB replaced in Agribeth Lathage. Details not found yet.
7	2003	1112 Page 14	problems and repair methodology discussed (AIChE paper reference available).
8	2003	0708 Page 12-18	WHB incidents and conclusions with references to AIChE papers. Full Article available.
9	2005	1112 Page 16	Optius tube replacement and WHB replacement experience. AIChE paper available. Synthesis loop.

World Fertilizer Magazine

Sr. No.	Year	Reference	Description
1	2008	20 Page 58	Plug a plug technique used in fertilizer plant located in Qatar. Full article available.