

Inadequate  
Horizontal Reinf.

Bursting  
stress

Crack Line

