
FILE NAME = 400559, opb., ote, don DATE/TIME = 84-DEC-2813 13:49 USER = vzornos

ALTERED BY: STATE OF NEW PORT POFESSIONAL TITLE

TOP OF NEW OVERLAY SHALL MATCH THE EXISTING DECK ELEVATION AND CROSS SLOPE EXISTING *5 UPPER BAR OF TOP REINFORCING BAR MAT. TO REMAIN 5" NAX ITEM 581.02 -1" MIN. LOWER LIMIT OF CONCRETE REMOVAL, EXCEPT FOR LOCALIZED AREAS, SEE REPAIR PROCEDURE DETAIL. MINIMUM REMOVAL LIMITS WHERE CONCRETE IS REMOVED AROUND THE LOWER BARS OF THE TOP REINFORCING BAR MAT. EXISTING SOUND CONCRETE TO REMAIN

REINFORCING BAR EXPOSURE - BOTH BARS OF UPPER BAR MAT (LIMITS OF COMPLETE CONCRETE REMOVAL FROM AROUND UPPER AND LOWER BARS.)



REPAIR PROCEDURE LOCALIZED AREAS

NOTES:

- 1. CONTRACTOR TO COORDINATE WITH EIC FOR LOCATIONS AND LIMITS OF WORK.
- 2. IT IS ASSUMED THAT 5% OF THE DECK AREA WILL REQUIRE A FULL DEPTH REPAIR AS SHOWN ABOVE.

AS-BUILT REVISIONS DESCRIPTION OF ALTERATIONS:	BRIDGE REHABILITATION ROUTE 5 & 20 IN GENEVA	PIN 4005.59 5 & 20 UTILITY QUALITY LEVEL C	BRIDGES 1001939	CULVERTS	ALL DIMENSIONS IN ++ UNLESS OTHERWISE NOTED	CONTRACT NUMBER
	BIN 1001939 SH 52-10				CONCRETE OVERLAY DETAILS	D262543
					ROUTE 5 & 20	DRAWING NO. ST1-33
	COUNTY: ONTARIO				OVER HORFOLK SOUTHERN RAILROAD	SHEET NO. 37

