

- P1 AND P2 ARE PIN \varnothing 'S
- P3 PASSES THROUGH P1 AND P2 AND IS PERP TO A
- P4 PASSES THROUGH P1 AND IS PERP TO DATUMS A AND P3
- DATUM A IS THE 4 CORNER PADS
- FLATNESS UNLESS OTHERWISE SPECIFIED IS .001" \ 1.00" X 1.00" PER A WORKMANSHIP STANDARD

