

API 571 - MIC

4.3.8.5 Appearance or Morphology of Damage

b) Damage is often characterized by cup-shaped pits within pits in carbon steel

MIC – API RP 571



4" GAS LIFT LINE

