

The damaged disc



The new disc



Lost more than 50%
of the seating surface




Seating surfaces

The damaged Nozzle




The new Nozzle



0.9 mm

Nozzle deformed
and lost around 50%
of their seating
surface



1.6 mm