

- H Discharges in Cooling Duct, mainly created by vibration & abrasion of corona protection layers
- I Delamination of insulation in Elbow, especially when manually manufactured
- J End winding discharge (contamination, etc.)
- K Insufficient spacing, tracking; especially between bars with big voltage difference, different phases
- L Connection area between slot corona protection & end winding corona protection