

DCP_3490
Shrinkage
exacerbated
by expansion



4.9.2009



DCP_3491
Primarily
shrinkage

4. 9. 2009

DCP_3492

Shrinkage

crack



4. 9. 2009

Note double
cored hole



DCP_3493

Expansion



Expansion



This may have
started as shrinkage



4.9.2009

A close-up photograph of a concrete curb. A dark metal plate is mounted on top of the curb with two screws. The concrete shows several prominent expansion cracks, particularly one that runs vertically down the side of the curb and another that runs horizontally across the top surface. The background shows a concrete sidewalk with shadows cast by a fence or railing.

DCP_3494
Clearly expansion
cracks

4. 9. 2009