



CRACKING OCCURED HERE AS WELL, THIS IS A WELD DESIGN PROBLEM, THE COMPAD HAS POINTED CORNERS! THE CRACK HAS RUN AS SHOWN & I BELIEVE IT IS JOINING UP ALL THE FATIGUE CRACKS, WHICH ARE ALSO FATIGUE BUT A SEPERATE MECHANISM.