


Legend

1. Lighting Hung From Roof.
2. Failure of W24 \times 76 Beam.
3. Top Flange.
4. Supported W24 \times 94 Beam.
5. Bottom Flange Buckles.
6. Web Bent Horizontal.
7. Column Top Displaced 21" South.
8. Canopy Hung From Roof.
9. Mechanical Equipment Hung From Roof.
10. Open Web Steel Joists.
11. Broken Water Pipe.



(Trevor Burkitt Photo)