



* This surface was lowered by
0.35" endbells = mounting
Bolt pattern should be
adjusted

Bolt circle needs
to be lowered