

Thanks to all of you your contributions. I should have also added that the chain drive is on a 45° slope. Please find below the arrangement I currently have.

