




Damaged DO boards of Transformer Protection IED

#1 DO board



#2 DO board






Varistor 파괴

PCB Pattern 절단 및 교류전압에 의한 Arc Over

Soots evidence resulted from
SPD damages



Damaged Surge Protector in AC Power Panel