



bad corner - vertical cracks at corner, and wall going to the left has moved inward at the top



different bad corner. lots of cracking and out-of-plane movement



another bad spot. back wall with 4" deflection. CMU buttress and original wood "repair" - sheared off from rot





further along that same back wall. still lots of movement.



vertical cracking at the corner in the first picture, and out-of-plane movement outward.



grey "pot clay", somewhat covered by red clay runoff