




CASE #1 – hole positioned to A, B, C



CASE #2 – hole positioned to B, C



OBSERVATION:

The very same part meets position tolerance in case #1, but does not meet position tolerance in case #2.

CONCLUSION:

Dimensioning and tolerancing schemes shown in both cases are not equivalent.

