



Based on previous failure pattern, the present data indicates, change in the coupling balance condition and most probably by breaking of the shim pack elements.