

As-found, One pack disassembled, one not. Both had same pattern when later disassembled (shows on inner surfaces of shims, not outer surface). They felt greasy. Note the only place the pattern does not occur is the outer surface of outer shims-> suggests fretting



After cleaning – photos note shims were replaced, not re-used)



More after-cleaning photos



More after-cleaning photos



More after-cleaning photos



More after-cleaning photos

