

TOP COAT MATERIAL IS
AFFECTED DUE TO
BLASTING

