




# TUBE DAMAGE LOCATION AND STATUS

Location : Drain Nozzle (2ND Baffle from Tube Sheet)  
At 3 Pass and 4Pass Area




1. Tube Surface Pitting








2. Friction Damage at Baffle



3. Tube Surface Pitting and Micro Crack



4. Tube Surface near by Tube Sheet





5. Micro Crack (Max. 1.1mm)

