
the case of blanked stampings, the tolerances apply to the cut band (see figure 1).



ote. Where the position and size of the draw-in band, break band and burr may affect the functioning of the stampir

Measuring to a stamping edge...what area is considered a "broken edge"