



The arrowed beam got torsion and it failed in shear design by staad.



