




# Key damage –replaced



## 22c Impeller keyway damage... replaced



Presumed  
wear  
against key



Shaft keyway damage.

