



BENDING IN SLAB DUE TO
OFFSET OF VERTICAL
COMPONENT OF PT FROM
SUPPORT.

