




Legs' bottom plates checked with 100% MPI (Acceptable)



Sign of Leak in Some Zones Before entry inside the Deck



Roof Plate inside the Deck through Sample Port



Cracked Concrete Ring