

Rough sketch of bearing arrangement in shaft based on strip down of failed unit (anti-rotation device may be shown reversed)

Concern is that the grease cannot get to ball bearing due to presence of anti-rotation device and the locking bolt for the anti-rotation device, which largely fills the slot where it locks the outer part of the anti-rotation device.









Grease path to roller bearing restricted by locking bolt