



2a - Responses, Photo reference - #1



Section 5.4 in WSP's geotech report for site specific, F-014a indicates no groundwater and that the soil was wet about 2.1m.

Section 6.1 in WSP's geotech report generalizes all the sites in the report and states that "significant groundwater seepage may also be encountered from adjacent utility trench backfill / pipe bedding where excavation for construction of the proposed chambers exposes these materials".

Given the photos above, the "significant groundwater seepage..." seems to be quite significant and from KCL's point of view should've been detailed or shown in the drawings had this been known. KCL believes that is was not included because notes were taken in Section 5.4 rather than note taken from Section 6.1.