


Stator. Arrows show discontinuity in lam appearance. (Newer looking closer to camera) End laminations were flared out during coil stripping



Stator tested again (vertically). Discontinuity in lams shows here (I think the newer shows up hotter)

