

Photo 3: Flange outer surface after cleaning showing pits ( yellow arrows)and pit with hole/leak (A).




Photo 4: Inner surface corresponds to Photo 3.