

Photo 1: Showing the affected locations before the the polyurethane outer cover and the the deposit on the flange were removed.




Photo 2: Showing the affected locations after the the polyurethane outer cover and the the deposit on the flange has been removed.