



Faulty Rotor TIR Map



Faulty Rotor




Another view of sister rotor, identical design



04/03/2007

Sister rotor, non-identical design (used with the same stator / frame, but OEM redesigned the rotor – this is a different generation)



Copper Liner around bars in slots.

