
Customer Defaults
Defaults Level
User
Default Lock State
Unlocked
Units Syste
Gateway
Modeling
Sketch
Animation Designer
Curves
Analysis
Assemblies
Drafting
Layout
PMI
Technical Data Package
Manufacturing
General
User Interface
Operation
Geometry
Selection
Tool Path Display
Simulation & Visualization
Post Configurator
Colors
Optimize Tool Path
General
Tool Path
Machining Data
Automatically Set in Operation
Always Change Stepover Type to Constant
Feed per Minute Decimal Places
1
Preview
Floor and Wall Milling Preview
Projection Preview - Max Vectors to Display
User Defined Operations
User Defined Operation Prefix
Legacy
Retrieve Template with Tool (Obsolete)
Allow On-plane Stepover Option in Area Milling
Allow Legacy Drive Methods in Fixed Contour