
Worn Shaft (smooth and shiny surface)
(Bush not shown here)
Bush
A
B
Worn Shaft (smooth and shiny surface)

Bush-showing lubrication groove


Worn Shaft (rough surface)- position where in line shaft bush is placed
To motor
D
C
To impellers