Gap Created by
Expansion of Pipe

Expansion

(a) **WRONG** Installation with an Anchor

Anchor

F   F   F

(b) **CORRECT** Installation with Sliding Support

F   F   F   F

P

Move

Sliding
Support

FIG. 7.28
A SITUATION WHEN ANCHOR IS THE PROBLEM