According to crack pattern survey, this corner of the building moves towards arrow direction.