



Vendor recommends checking run out here (Tolerance 0.25mm per meter)