



### STAGES OF ELECTRICAL DISCHARGE FAILURE.

1. FROSTING
2. PITTING
3. SPARK TRACKS
4. WEEDING
5. MELTING