



There are three ways to specify a datum center plane :

1. The datum feature symbol can be in line with a dimension line and touching the extension line on the opposite side of the dimension line arrowhead of a FOS



2. The datum feature symbol can replace one side of the dimension line and arrowhead of a FOS dimension.



3. The datum feature symbol can touch a FCF which is applied to a FOS.

