



THREE - PHASE MOTORS - TWO SPEED. IEC NOMENCLATURE - 6 LEADS

CONSTANT TORQUE CONNECTION



SPEED	L1	L2	L3		REMARKS
HIGH	2W	2U	2V	1U & 1V & 1W join	2WYE
LOW	1U	1V	1W	2U-2V-2W OPEN	1 Δ

VARIABLE TORQUE CONNECTION



SPEED	L1	L2	L3		REMARKS
HIGH	2W	2U	2V	1U & 1V & 1W join	2WYE
LOW	1U	1V	1W	2U-2V-2W OPEN	1WYE