


If you extend the LP tubing above upper tap by about 2 ft it prevents liquid entering on accidental overflow

Use a tee or condensate pot for steam or other condensing liquids - fill with fluid at plug



Sometimes a small purge is required using air or nitrogen

