


Basic dimensions removed for clarification purposes

Blue lines - Defines Marker (Reference) K

Features in red – Actual location of pins and holes in relation to Marker K – Physical location Diameter C is not determined at this phase.

NOTE: Distance between all centers was exaggerated to a better understanding



Green lines- Best fit of marker K to the centers of pins PP1 to PP6 (Marker K when applied best fit had a translation and rotation). Check the distances between the centers of circles-holes (each one)