


Quote (ASME Y14.5M-1994 1.8.9 of):

The depth dimension of a blind hole is the depth of the full diameter from the outer surface of the part.

THIS ON THE DRAWING:



**MEANS WHICH ONE?
TO BE IN ACCORDANCE WITH Y14.5**

