



"Best" Way to Design

- ① Design Beam for shear & moment Diagram
- ② Start & Tie ← How?
- ③ Some sort of Modified Gerber Method

Short Cantilever Beam