


2ND FLOOR

AXIAL LOAD DUE TO DEAD LOAD



2ND FLOOR PLAN