



$$2P \times \mu = 2F$$

$$T = 2F \times R$$

$$\tau = \frac{T r}{J}$$

$$J = \frac{\pi (D^4 - d^4)}{32}$$

$\tau$  = Average Shear Stress