



No load VA (losses) of XFMR: 300VA (Max)

Max Current of XFMR: 2A

Max Voltage of XFMR: 600VAC