

Case	a (size tolerance)	b (Circular runout)	c	DML redundant: Yes or No
A1	0.010	0.005	0.011	
B1	0.010	0.005	0.010	
C1	0.010	0.005	0.006	
D1	0.010	0.005	0.005	
E1	0.010	0.005	0.004	
A2	0.005	0.010	0.011	
B2	0.005	0.010	0.010	
C2	0.005	0.010	0.006	
D2	0.005	0.010	0.005	
E2	0.005	0.010	0.004	

Case	a (size tolerance)	b (Total runout)	c	DML redundant: Yes or No
F1	0.010	0.005	0.011	
G1	0.010	0.005	0.010	
H1	0.010	0.005	0.006	
I1	0.010	0.005	0.005	
J1	0.010	0.005	0.004	
F2	0.005	0.010	0.011	
G2	0.005	0.010	0.010	
H2	0.005	0.010	0.006	
I2	0.005	0.010	0.005	
J2	0.005	0.010	0.004	

