



Losses reduction improving power factor from $PF_0 = 75\%$ to a target power factor of $PF_{target} = 95\%$

$$\Delta Losses := Losses_0 - Losses_{target}$$

$$\Delta Losses = 0.9\%$$

