


11B Vapor Extractor seal. (zoom-in next slide)





Two rubber seals lip seals, with grease in between.





Motor Shaft Before repair (not a great picture)



Repaired motor shaft. Machinist repaired the two areas that had grooves in as-found condition by using Speedi-Sleeve. I think these two areas correspond to the lip seals

