



$f'_c = 6,000 \text{ psi @ 28 days}$
 $f'_{ci} = 3,850 \text{ PSI @ transfer}$

CAMBER $\triangle i = \frac{3}{4}"$
 CAMBER $\triangle 30 = 1\frac{1}{4}"$