
Pinion Thrust Collar having Face Run out running against perfect Bull Gear Face



Perfect Pinion Thrust Collar running against perfect Bull Gear having Face Run out (due to position of shaft within Bearings or due to run out on Gear Face or combination of both)

